



R1- SAINT WIEN PROGRAMMABLE RATE METER

R-Series is a programmable indication and control meter with features like Pre-Scale Factor, Hysteresis, Delay Time, Offset, and Display Hold. Its powerful single chip CPU and excellent software design provides users a high flexibility for a variety of applications.

1. Ordering Information:



2. Front Panel*:



*For R1-6DO-XXXX

3. Electrical and General Specifications:


1. Supply voltage: 24/110/220 (±10%) VAC 50/60Hz
2. Power consumption: 3~7VA approx.
3. Ambient conditions: -10~55°C, 35~85% RH
4. Weight: 300~600g approx.
5. Display: Model R1-6DXXXX--- 6 digits
Model R1-4DXXXX--- 4 digits
6. Protection:
 - EEPROM memory backup
 - Watchdog Timer
7. Indication Accuracy: 0~999999 ±0.01%; ±1 count; ±50ppm/°C; Range 4~300,000RPM
8. Sampling time: 100ms to 16.5 s. Varies according to input signal frequency
9. Resolution: 0.01~10RPM , depending on display range
10. Delay time: 0~99s. Turns the output ON after the delay time is elapsed
11. Offset: 0~999999 (R1-6DXXXX), or 0~9999 (R1-4DXXXX). Display starts from the offset value, instead of 0.
12. Hysteresis: 0~9999
13. Decimal Point: 3 positions for PV, P1, p2, Offset and Hysteresis

4. Input and Output Specifications:

1. Signal Input CP1 : 5~30VDC input. Single or Multiple pulses per revolution
2. Hold Input CP2: A high input on CP2 will hold the display count until CP2 input goes low.
3. Power for Sensor: 12VDC (±15%) 60mA(R1, R2); 20mA(R3)

5. Configuration of R1:


5.1 Setting Preset Values:



- i. Press [M] at the Process value screen to enter Preset-1 screen.
- ii. Press [<] to select the required digit. The selected digit flashes
- iii. Press [^] to increment the value.
- iv. Repeat steps ii, iii to all digits of Preset-1.
- v. Press [M] to enter Preset-2 screen.
- vi. Repeat steps ii, iii to all digits of Preset-2.
- vii. Press [M] to save presets and return to Process Value screen.

viii. Press [uR] to save the settings to the CPU.


5.2 Configuring Offset and Prescalers:



- i. Press [M] while holding [<] at the process value screen to enter OFFSET screen. OFFSET defines the starting value for the rate meter. The value specified in OFFSET is always added to the actual process value.
- ii. The OFFSET value and the display 'OFST' swap every 3 seconds.
- iii. Press [<<] to select the required digit.
- iv. Press [^] to increment the value at the selected digit.
- v. Repeat steps iii, iv for every digit in OFFSET screen.
- vi. Press [M] to save the OFFSET value and enter 'IN' screen.
IN and DSP decide the input prescale. The Process value is given by

$$\text{Process Value} = \frac{\text{DSP}}{\text{IN}} \times \text{Number of Pulses received per minute}$$
- More information on DSP, IN has been provided in Appendix-1.
- vii. Repeat steps iii, iv to set the IN value
- viii. Press [M] to save 'IN' value and enter 'DSP' screen.
- ix. Again, repeat steps iii, iv to set DSP value.
- x. Press [M] to save DSP and return to process value screen.
- xi. Press [uR] to save the settings to the CPU

5.3 Configuring Delay and Hysteresis of Output:



- i. At the Process Value screen, press [M] while holding [^] to enter into Delay screen.
- ii. Use [<<] to select the required digit.
- iii. Press [^] to change the value at selected digit.
- iv. Repeat steps ii, iii for all digits in the Digit screen.
- v. Press [M] to save the Delay value and enter Hysteresis screen.
- vi. Again, repeat steps ii, iii to enter a Hysteresis value.
- vii. Press [M] to save the Hysteresis value and return to Process value screen.
- viii. Press [uR] to save the settings to the CPU.

5.4 Adjusting the decimal point:

- i. At Process Value screen, press [uR] repeatedly while holding [<] key to change the decimal point to the desired position.
- ii. Press [uR] to save the settings to the CPU.

5.5 CPU Reset:

NB: Resetting the CPU will erase all the programmed parameters.

- i. Power up the R1 while holding [M],[^],[<] keys simultaneously. This resets the CPU erasing all the programmed parameters. Re-configure R1 for new function.

Appendix-1: Configuring R1 to display RPM:

If 'n' pulses are produced for every 'r' rotations, then to display RPM, set
OFST=0
DSP=r
IN=n

Example: If 10 pulses are produced for 1 rotation of the shaft, then settings are as follows.
OFST=0
DSP=1
IN=10

This would configure R1 to display RPM. Adjust the decimal point appropriately.

Appendix-2: Configuring R2 to display line speed:

R1 could be configured to display the line speed of a conveyor belt system.

Measure the diameter of the shaft.

Let Diameter of shaft = d

So, Distance traveled in 1 rotation of the shaft = $3.14 \times d$

Let, Number of pulses received for one rotation = x

The parameters to display line speed are as shown below.

OFST = 0
DSP = $3.14 \times d$
IN = x