# TW-DA Digital to Analogue Converter.

Features.

- Programmable V or mA Outputs.
- Rangeable from 2 to 6 Digital Inputs
- Bi-Polar Digital Inputs.
- Isolated Input to Output 1600V.
- Low Cost.
- Easy to Install.
- Compact DIN Rail Mount Enclosure.
- Reverse Polarity Protection.
- Adjustable Span & Zero.



Isolated Parallel Digital Input to Three Wire V or mA

Analogue Output Converter.

# Description.

The TW-DA is designed primarily for low cost digital to analogue conversions for PLCs, controllers, etc. Digital inputs are converted in binary to analogue V or mA outputs.

## Ordering Information.

TW-DA-X Standard Unit, 4 Digital Inputs, 4~20mA Output.

TW-DA- - D AO

Special Range Calibration.

INPUTS		OUTPUTS	
Number Of Digital Inputs	D	Analogue Ouput	AO
2 D/I	2	4~20mA	А
3 D/I	3	0~20mA	В
4 D/I	4	2~10V	С
5 D/I	5	0~10V	D
6 D/I	6		

# Ordering Examples.

TW-DA: 6 Digital Inputs; 4~20mA Output.

TW-DA-2-D TW-DA; 2 Digital Inputs; 0~10V Output.

## Quality Assurance Programme.

The modern technology and strict procedures of the ISO9001 Quality Assurance Programme applied during design, development, production and final inspection grant the long term reliability of the instrument.


### TW-DA Specifications.

lications.	
	6 Opto-Isolated Inputs with LED Indication for each Input.
: All Inputs have one	e common that can be connected to '0V' or '+V'.
	6~30Vdc.
9	5.5V Typical.
@ 6V	1mA per Channel Typical.
@ 12V	4mA per Channel Typical.
@ 20V	8mA per Channel Typical.
@ 24V	9mA per Channel Typical.
	Binary. N.O. Contact = '0', N.C. Contact = '1'.
;	
	0~10V, 2~10V.
	5mA Maximum. (2kΩ @ 10V.)
	0~20mA, 4~20mA
<ul> <li>Output Drive</li> </ul>	10V Maximum. (500Ω @ 20mA.)
	From 2 to 6 bits. (4 to 64 steps.)
	24Vdc±6Vdc. LED Indication of Power Supply.
	40mA Typical at 24Vdc P/S. (No allowance for Digital Inputs.)
- 10V O/P	22mA Typical at 24Vdc P/S. (No allowance for Digital Inputs.)
	Selected Resolution <±1% FSO Typical.
tability	<±1% FSO Typical.
	<±0.02%/C FSO Typical.
	Emissions EN 55022-A. Immunity EN 50082-1, <1% Effect FSO Typical.
•	Digital Inputs to Analogue Input/Outputs: 1600Vdc for 1min.
	0~70C.
	-20~80C.
ty	5~85%RH Max. Non-Condensing.
	DIN & EN Rail Mount Enclosure.
	L=90mm, W=78mm, H=45mm.
	180g (Includes Packaging).
	: All Inputs have on @ 6V @ 12V @ 20V @ 24V


**Product Liability.** This information describes our products. It does not constitute guaranteed properties and is not intended to affirm the suitability of a product for a particular application. Due to ongoing research and development, designs, specifications, and documentation are subject to change without notification. Regrettably, omissions and exceptions cannot be completely ruled out. No liability will be accepted for errors, omissions or amendments to this specification. Technical data are always specified by their average values and are based on Standard Calibration Units at 25C, unless otherwise specified. Each product is subject to the 'Conditions of Sale'.

Warning: These products are not designed for use in, and should not be used for patient connected applications. In any critical installation an independant fail-safe back-up system must always be implemented.

## TW-DA Connection Examples. Common '0V' Input.



Common '+V' Input.




Note 1. N.O. Contact is '0' N.C. Contact is '1' Code is Binary.

- Note 2. The COM of the inputs can connected to the +ve or the -ve of the input power supply.
- Note 3. Solid state outputs are recommended for powering the digital inputs. If electro-mechanical relays are used contact bounce may cause momentary false outputs.
- Note 4. The same power supply can be used to power up both the input and output of the TW-DA. Note that this will however void the isolation between input and output.



# TW-DA PCB Layout - Location of H1 and H2 for Programming.



## *TW-DA Programming.* Selecting the Analogue Output.

Refer to the picture above for the location of the Headers on the PCB.

For 4~20mA output place the jumpers in the following positions:

For 0~10V output place the jumpers in the following positions:

For 0~20mA output place the jumpers in the following positions:

For 2~10V output place the jumpers in the following positions:

#### Selecting the Number of Digital Inputs.

Using 2 Digital Inputs gives 4 output steps:33.3% per step.Using 3 Digital Inputs gives 8 output steps:14.3% per step.Using 4 Digital Inputs gives 16 output steps:6.67% per step.Using 5 Digital Inputs gives 32 output steps:3.22% per step.Using 6 Digital Inputs gives 64 output steps:1.59% per step.MSB = Most significant bit. LSB = Least significant bit.

H2
V
H1
H2
H1
H2
E 🔳 🖬 🖊
H1
H2
⊴∎∎∎
H1

Use B32 for MSB, & B16 for LSB. Use B32 for MSB, & B8 for LSB. Use B32 for MSB, & B4 for LSB. Use B32 for MSB, & B2 for LSB. Use B32 for MSB, & B1 for LSB.

#### Calibrating the TW-DA to the Required Ranges. Note: To range the unit select the output range first.

1/ With no digital inputs active use the ZERO Pot to calibrate the 0% point.

Note: When adjusting 0~10V or 0~20mA ensure you do not overwind the ZERO Pot. A slight offset may be left. Wind the zero reading down until it just makes it's minimum value.

- 2/ Activate the number of digital inputs to be used and use the SPAN Pot to calibrate the 100% point.
- 3/ Repeat 1/ and 2/ until no more adjustment is required.
- 4/ Do a mid point check to confirm your calibration.
- 5/ Label the unit with the number of digital inputs and the type of analogue output selected.

# The Proper Installation & Maintenance of TW-DA.

All power and signals must be de-energised before connecting any wiring, or altering any Jumpers or Dip Switches. **MOUNTING.** 

- (1) Mount in a clean environment in an electrical cabinet on DIN or EN rail.
- (2) Do not subject to vibration or excess temperature or humidity variations.
- (3) Avoid mounting in cabinets with power control equipment.
- (4) To maintain compliance with the EMC Directives, the TW-DA must be mounted in a fully enclosed, metal, electrical cabinet. The cabinet must be properly earthed, with appropriate input / output entry points, cabling and filtering.

#### WIRING.

- (1) All cables should be good quality overall screened INSTRUMENTATION CABLE with the screen earthed at one end only.
- (2) Signal cables should be laid a minimum distance of 300mm from any power cables.
- (3) For 2 wire current loops and 2 wire voltage signals or 2 wire current signals, Austral Standard Cables B5102ES is recommended. For 3 wire transmitters Austral Standard Cables B5103ES is recommended.
- (4) It is recommended that you do not ground current loops and use power supplies with ungrounded outputs.
- (5) Lightning arrestors should be used when there is a danger from this source.
- (6) Refer to diagrams for connection information.

#### COMMISSIONING.

- (1) Once all the above conditions have been carried out and the wiring checked apply power to the TW-DA loop and allow five minutes for it to stabilize.
- (2) Take a low (approx. 10%) and high (approx. 90%) reading of the variable being measured by the transducer supplying the signal to the TW-DA, and ensure that this agrees with the level being indicated by the PLC or indicator, etc., that the TW-DA is connected to. Adjust for any difference using the Zero & Span Pots in the top of the TW-DA enclosure with a small screwdriver, until the two levels agree. (Clockwise to increase the output reading and anticlockwise to decrease the output reading.)

#### MAINTENANCE.

- (1) Repeat (2) of Commissioning.
- (2) Do it regularly at least once every 12 months.

